

APPROVAL OF SERVICE SUPPLIERS

This is to certify that

Global Marine Safety (Singapore) Pte Ltd

SINGAPORE, Singapore

is granted acceptance for

Inspection and testing of radio communication equipment and Automatic Identification Systems (AIS) , in accordance with Class Programme DNVGL-CP-0484.

This service supplier certificate will be accepted for use with all rule sets published by DNV GL.
See the following page(s) for details regarding application.

This Certificate is valid until **2020-04-24**.

Issued at **Certification of Materials - Singapore** on **2017-04-25**



for **DNV GL**

This document has been digitally signed and
will therefore not have handwritten signatures

Tan, Jyh Shu

**Head of Section, Certification of Materials
& Components, Singapore**

This Certificate may be withdrawn if:

1. The service provided has been improperly carried out or the results improperly reported.
2. The surveyor has found any deficiencies in the accepted operating systems of the service supplier.
3. The firm has failed to inform of any major changes having effect on the quality of the service rendered.
4. The conditions listed in the certificate are changed and/or are not fulfilled.

Certificate No: **AOSS0000CU9**

Application:

Approval Conditions:

1. This approval is subjected to annual review by the Society.
2. If changes are made to the approved system, such changes shall be reported to the Society for approval. Re-audit will be deemed necessary by the Society.
3. This Certificate is only valid for radio surveys carried out by the following personal, as long as they are employed by Global Marine Safety (Singapore) Pte Ltd

| NAME | ID | QUALIFICATION | POSITION |
|---------------|-----------|---------------|------------|
| SATISH BAKALI | G5494048W | GOC | SUPERVISOR |

4. The Service supplier's first DNV GL GMDSS and AIS survey job shall be properly verified by attending surveyor and report shall be sent to DNV GL Singapore for review.

Cancellation of approval:

The approval may be cancelled in case:

1. The service provided is improperly carried out or the result are improperly reported.
2. The society's surveyor has found major deviations in the operating system of the firm.
3. The firm fails to inform of any alteration to the operating system.